





HIGH PRESSURE SPRAYING MAY CAUSE THE ELBOW SADDLE TO ROTATE AND WORK THEIR WAY OFF THE TL START GROW UNIT. NOTE ILLUSTRATIONS 1, 2 & 3.

AVOID THIS PROBLEM BY:

- 1.) USING A WIDER, LESS CONCENTRATED SPRAY PATTERN
- 2.) NOT DIRECTING THE SPRAY DIRECTLY AT THE ELBOW **SADDLE**
- 3.) CREATING SUFFICIENT DISTANCE BETWEEN THE SPRAY **NOZZLE AND ELBOW SADDLES**

NOTE ILLUSTRATION 4.

ZIGGITY SYSTEMS	RECOMMENDED TL START GROW	
WWW.ZIGGITY.COM	DATE:	12-03-0

SPRAYING PROCEDURES: **SYSTEMS**

PART NR.:

12-03-04 IDAIE:

REVISION:

GL1045