



FAILURE TO USE 3/32" OR 2.4 MM O.D. 1 X 7 GALVANIZED CABLE WILL MOST LIKELY REQUIRE PERIODIC RE-TIGHTENING OF THE ANTI-ROOST SYSTEM AND/OR REPLACEMENT OF THE CABLE AND INSTALLATION ASSEMBLY HARDWARE.



HEAVY DUTY ANTI-ROOST CABLE INSTALLATION WITH SHORT CABLE LOOP

PART NR.:

DATE: 06-07-17

REVISION: 2

GL1087