


ITEM	PART NR.	QTY	DESCRIPTION
1	2639	1	BRACKET ASSEMBLY: ANTI-ROOST
2	1460	2	INSULATOR ASSEMBLY: ANTI-ROOST
3	2667	8	CLIP: ANTI-ROOST CABLE- HEAVY DUTY
4	2698	1	TURNBUCKLE
5	2669	1	SPRING: ANTI-ROOST - HEAVY DUTY



FAILURE TO USE 3/32" OR 2.4 MM O.D. 1 X 7 GALVANIZED CABLE WILL MOST LIKELY REQUIRE PERIODIC RE-TIGHTENING OF THE ANTI-ROOST SYSTEM AND/OR REPLACEMENT OF THE CABLE AND INSTALLATION ASSEMBLY HARDWARE.



INSTALLATION ASSEMBLY: HEAVY DUTY ANTI-ROOST  
- ADD-ON

PART NR.:

DATE: 06-08-17

REVISION: 1

2971