


Field Fix for sagging **Inline Riser Assemblies** that were introduced on March 1, 2022 on Info Update 2057.

Based on the type of drinker line pipe (Ace or Big Ace/Big Z/1" PVC) install the Field Fix Assemblies as noted in the chart and illustration below.


Inline Riser Assembly:	Field Fix:
PN 3977 (Ace Version)	PN XP-00547 ASSEMBLY: ACE CLIP-ON BRACKET W/SCREWS
PN 3971 (Big Ace/Big Z/1" PVC Version)	PN XP-00532 ASSEMBLY: MODIFIED CLIP-ON BRACKET W/SCREWS

RISER ASSEMBLY
NOT INCLUDED



ACE VERSION
PN XP-00547
ASSEMBLY: ACE CLIP-ON BRACKET W/SCREWS

RISER ASSEMBLY
NOT INCLUDED



BIG ACE/BIG Z/1" PVC VERSION
PN XP-00532
ASSEMBLY: MODIFIED CLIP-ON BRACKET W/SCREWS